

DIXON DISTRICT PARK

Mr. Bob Olson
112 E Second St
Dixon, IL 61021

Dear Mr. Olson:

Thank you for the opportunity to submit three of our funding proposals to the County's ARPA Committee for their consideration. We have prioritized our requests, with this proposal - a request for \$755,503 for the repaving of the roads of Lowell Park (2114 Lowell Park Road, Dixon) - being our top priority.

This project is our number one priority due to Lowell Park being used by so many residents of Lee County, not to mention the volume of visitors from Illinois and other parts of the United States. We are very grateful for the increase in the use of the park and the road improvements will greatly benefit our patrons. The grant will allow us to complete this project and keep Lowell Park a top destination for years to come.

The usage of Lowell Park has increased in the last three years due to the addition of disc golf, a new zip-line playground and the corn hole game. Covid-19 is also a huge factor in the considerable increase of people visiting this park. The community and visitors are wanting to get out and enjoy outdoor activities. Lowell Park is used by visitors from all over Lee county along with Dixon residents and out of town visitors.

The repaving of Lowell Park roads is in dire need to be completed. The base of the roads are satisfactory at this time, but as time goes on the base will start to break down, meaning two times the cost to repair the damage to the roads. All the other amenities are in great shape at Lowell Park. The restrooms, shelters, boat ramps, playgrounds, Woodcote Cottage, disc golf, cornhole game, security cameras, and the Ruth Edwards Nature Center are welcoming to park users. The Dixon Park District has applied for a \$80,000 grant for a canoe launch to add to the amenities Lowell Park has to offer.

The cost breakdown for this road improvement project is as follows;

Main Gate Area:	\$53,000
North Loop Road:	\$209,475
Pinetum Loop:	\$61,866
Hairpin Road:	\$187,845
Lower River Road:	\$152,817
Woodcote:	\$30,000
Lions Parking Area:	\$10,000
Engineering:	\$50,000

*Over 1100 acres of recreational space and natural area
28 sites including historic Lowell Park where President Reagan served as a lifeguard for seven summers*

DIXON PARK DISTRICT

The engineering and all bidding will be completed by Willett & Hofman and Associates to keep the tax dollars local. A series of photos showing the deterioration of these roads in Lowell Park are included as exhibits to this proposal. If you would like to schedule a time when we can visit the Park together, I will make myself available for such a meeting.

In recognition of this grant, provided funding is awarded, we will install a permanent sign at the entrance of Lowell Park to inform people that Lee County granted the funds to repave all the roads at Lowell Park. Examples of this signage has been included in this packet of information.

Thank you for your consideration of our request. The total cost estimate for this project is \$755,503. Meanwhile, should you have any questions, please feel free to contact myself, at (815)284-3306 or send me an email at: director@dixonparkdistrict.com.


Sincerely,

Duane Long
Dixon Park District, Executive Director

ENCLOSURE


Beginning of Hairpin Road

Gravel and blacktop patches, mud on shoulders




Beginning of Hairpin Road

Blacktop patches, mud on shoulders




Beginning of Hairpin Road

Mud on shoulders



Beginning of Hairpin Road

Gravel and blacktop patches, mud on shoulders




Beginning of Hairpin Road

Area to be improved with pavement, mud on shoulders




Beginning of Hairpin Road

Surface failure, gravel area to be improved with pavement




Beginning of Hairpin Road

Surface failure, blacktop and gravel patches




Beginning of Hairpin Road

Surface failure, gravel area to be improved by pavement




Hairpin Road

Surface failure, blacktop patches




Hairpin Road

Crown in road extreme, surface failure




Hairpin Road

Surface failure, area to be improved by pavement




Hairpin Road

Surface failure, area to be improved by pavement




Hairpin Road


Surface failure, area to be improved by pavement



Hairpin Road

Surface failure, area to be improved by pavement





Hairpin Road

Mud on shoulder, area to be improved by pavement

Hairpin Road

Surface failure, area to be improved by pavement







Hairpin Road
Surface failure, gravel and blacktop patches


Hairpin Road

Surface failure, area to be improved by pavement






Hairpin Road
Surface failure, blacktop patches



Hairpin Road
Surface failure, crown in road extreme


Hairpin Road

Surface failure, crown in road extreme




Hairpin Road

Surface failure, gravel and blacktop patches




Hairpin Road

Surface failure, gravel and blacktop patches




Hairpin Road

Surface failure, gravel and blacktop patches




Hairpin Road

Surface failure, gravel and blacktop patches




Hairpin Road

Surface failure, crown in road extreme




Hairpin Road

Surface failure, gravel and blacktop patches



Hairpin Road

Surface failure, gravel and blacktop patches



Hairpin Road

Surface failure, erosion onto roadway, gravel and blacktop patches



Hairpin Road

Surface failure, erosion onto roadway, gravel and blacktop patches




Hairpin Road

Surface failure, crown in road extreme, mud on road shoulder




Hairpin Road

Surface failure, blacktop patches




Lower Main Road

Surface failure, blacktop patches




Lower Main Road

Surface failure, blacktop patches




Lower Main Road


Surface failure, blacktop patches, mud on shoulders



Lower Main Road

Surface failure, blacktop patches, crown in road extreme






Parking at Lions Shelter
Gravel area to be improved with pavement


Parking at Lions Shelter

Gravel area to be improved with pavement




Parking at Lions Shelter

Gravel area to be improved with pavement




Parking at Lions Shelter

Gravel area to be improved with pavement




Lower Main Road/Parking

Gravel patches and gravel area to be improved by pavement



Lower Main Road/Parking

Gravel patches and gravel area to be improved by pavement



Playground Parking


Gravel area to be improved by pavement; muddy shoulders



Playground Parking

Ruts from parking in grass in area in need of paved parking area





Playground Parking

Ruts parking in area in need of a paved parking area


Playground Parking

Ruts from parking in grass in area in need of paved parking area




Woodcote Parking

Surface failure, mud on shoulders




Woodcote Parking

Surface failure, crown in road extreme




Woodcote Parking

Surface failure, crown in road, blacktop patches




Woodcote Parking

Surface failure, crown in road, blacktop patches




Woodcote Parking

Surface failure, gravel patches




Woodcote Parking

Gravel patches, mud on shoulders




Woodcote Parking

Ruts in grass, gravel patches




Woodcote Parking

Major area of gravel patchwork




Woodcote Parking

Surface failure, mud on
shoulder, gravel patches




Woodcote Parking


Surface failure, mud on
shoulder, blacktop patches



Woodcote Parking

Surface failure, mud on
shoulder, gravel patches





Woodcote Parking

Surface failure, mud on
shoulder, gravel patches

Main Road

Surface failure, mud on shoulder, blacktop patches




North Loop Road

Surface failure, blacktop patches



North Loop Road

Crown in road extreme, erosion




North Loop Road

Crown in road extreme, surface failure, blacktop patches




North Loop Road

Surface failure, blacktop patches




North Loop Road

Crown in road extreme, surface failure, blacktop patches




North Loop Road


Crown in road extreme, surface failure, blacktop and gravel patches



North Loop Road

Surface failure, blacktop and gravel patches






North Loop Road

Crown in road extreme, surface failure, blacktop and gravel patches


North Loop Road

Gravel area to be improved with pavement




North Loop Road

Surface failure, blacktop and gravel patches, mud on shoulders




North Loop Road


Surface failure, blacktop and gravel patches, mud on shoulders



North Loop Road

Surface failure, blacktop and gravel patches, mud on shoulders






North Loop Road

Surface failure, blacktop patches

North Loop Road

Surface failure, blacktop patches




North Loop Road

Surface failure, blacktop patches




North Loop Road

Gravel area to be improved with pavement




North Loop Road


Gravel area to be improved with pavement



North Loop Road

Gravel area to be improved with pavement,
mud and erosions on shoulder






North Loop Road

Gravel area to be improved with pavement


North Loop Road

Gravel area to be improved with pavement



North Loop Road

Blacktop patches





Thank You

The Park District received \$750,000 from Lee County in 2022, allowing us to make road improvements and ensure Lowell Park's safety for years to come.



Thank You

The Park District received \$750,000 from Lee County in 2022, allowing us to make road improvements and ensure Lowell Park's safety for years to come.